



Note 1: C1, C2, L1 and C7 replace components originally mounted off-board by Ten-tec

Note 2: You may need more gain in the input amplifier if your HFO signal level is low, particularly on 17m where the frequency is highest

Note 3: Board needs to be 4.7"x3" with holes on 4.3" and 2.6" centres

Note 4: Approx 200uH air-cored choke. Use original Ten-Tec part, or approx 150 turns on a small bobbin

G3TXQ		
Corsair II MPU replacement		
S E Hunt	Rev 1.2	Page # or name
	28/08/2011	